

## SERVICE LETTER NO. SL GROB-022

### I. TECHNICAL DETAILS

#### **1.1 Airplanes affected:**

G 115, G 120, G 120TP S/N all as affected

#### **1.2 Subject:**

ATA-Code: 32-40 Wheels and Brakes  
Alternative NLG Wheel Rim Assy

#### **1.3 Reason:**

Due to obsolescence of the approved Nose Landing Gear (NLG) Wheel Rim Assy P/N 115C-5205, continued supply of spare parts cannot be ensured.

In order to maintain spare part availability and ensure continued fleet support, Grob Aircraft SE has approved the Tost NLG Wheel Rim Assy P/N 035305 as an alternative spare part.

This Service Letter is issued for information purposes only.

#### **1.4 Information:**

The IPC and AMM do not yet reflect this alternative part. Until incorporation in the next approved revision, the following instructions and limitations shall apply:

- Tost NLG Wheel Rim Assy P/N 035305 is approved by Grob Aircraft SE as an alternative part to Grob NLG Wheel Rim Assy P/N 115C-5205. No modification to the aircraft, the installation interface, or the installation procedure is required.
- Removal and installation of the NLG Wheel Rim Assy on the aircraft shall be performed in accordance with the applicable Grob AMM, Chapter 32-40, Wheels and Brakes.
- Maintenance of the Tost NLG Wheel Rim Assy P/N 035305 shall be performed in accordance with the applicable current Tost maintenance documentation. This includes, as applicable, wheel disassembly and reassembly for tire and inner tube replacement, regular cleaning and inspection, and bearing replacement where required.
- For Tost NLG Wheel Rim Assy P/N 035305, the maintenance instructions, inspection requirements, wear limits, replacement criteria, and specified torque values defined in the applicable Tost maintenance documentation shall apply.
- The Tost Wheel Halves are fitted with ball bearings P/N 6006-2RS.
- Components of Grob NLG Wheel Rim Assy P/N 115C-5205 and Tost NLG Wheel Rim Assy P/N 035305 **shall not be intermixed**.

Table 1: Part Number Interchangeability

Obsolete Part Numbers	Alternative Part Numbers
115C-5205 (Grob)	035305 (Tost)
115C-5205.01 (Grob)	-
115C-5205.02 (Grob)	-
035300 (Tost)	035305 (Tost)

## **II. REMARKS**

If you have sold your aircraft in the meantime, would you kindly pass this information on to the new owner and forward his address and aircraft S/N to us. For questions and assistance please contact:

Product Support,  
phone: +49 8268 998105  
fax: +49 8268 998200  
e-mail: [productsupport@grob-aircraft.com](mailto:productsupport@grob-aircraft.com)